Tele : 6417 (Mil)

226/C/ 160 /E2

Office of the AGE B/R-II Happy Valley, Shillong-07

& Pa

19 Feb 2020

Kendriya Vidyalaya Happy Valley, Shillong

TECHNICAL AUDIT OF BUILDING OF KENDRIYA VIDYALAYA HAPPY VALLEY

- Reference your office letter No F.50/KV Happy Valley/2019-20 dt- 16.10.2019.
- After the visual inspection of the KV Building. It is found that the building is structurally sound. However at some places minor cracks are visible which are safe and negligible. It can be repair by normal maint work.

(Amarjii Rabidas)
AE (Civ)
AGE B/R-II Happy Valley